7100.PGT120.SE
Pedestal Stand Assembly Kit

**Tester, gloves, and wrist strap not included*

Installation Instructions for PGT120 Stand

The PGT120 tests the functioning of ESD personal grounding equipment such as ESD shoes, heel grounders and wrist straps. The following are installation instructions for the PGT120 stand:

(1) **7100.PGT120.WK.H.US**
- Acrylic Mounting Plate



(1) **7100.PGT120.WK**
- Metal Wall Mount

(1) **7100.PGT120.WK.BK**
- Stanchion Bracket



(1) **7100.PGT120.SD**
- Yellow Post and Base

Also Included:
(1) Strip of Velcro Tape
(1) M8 Counter Sunk Screw with matching nut and fastener
(2) 8/32 Screw with matching nut

Step 1: Attach the yellow post to the base. Align the post socket onto the base bolt and spin to secure the post to the base



Step 2: Attach the bracket to the acrylic plate using the M8 screw, fastener and nut.

3719 King Road
Toledo Ohio 43617
Phone: 419-841-9552
info@transforming-technologies.com

Step 3: Attach the metal mounting plate to the acrylic plate with two screws



Step 4: Attach adhesive Velcro tape to the Data Terminal (p/n 7100.PGT120.COM.DT) and place underneath the metal mounting plate as shown below:

Step 5: Attach the PGT120 tester to the Velcro tape on the metal plate

Step 6: Use the Velcro adhesive tape to attach the accessories (such as printer, barcode scanner) to the top of the acrylic plate. Place the assembly onto the yellow pedestal stand to finish the assembly.

Finished Assembly

This document is prepared for our customers as a service, and is to the best of our knowledge true and accurate. However, it is understood and agreed by the users of this document that we will accept no liability for the conclusions reached. Users of this document may therefore wish to perform additional testing before determining that products mentioned are suitable.

3719 King Road
Toledo Ohio 43617
Phone: 419-841-9552
info@transforming-technologies.com